

⑧ WORTHINGTON
VCP
NEED REBUILT
8" LINE TO 6 3/4"
S/N L-87514A
MAWP 1000

⑨ WORTHINGTON
VCP
NEEDS REBUILT
10"
S/N A-14902
MAWP 1000

⑩ WORTHINGTON
VCP
NEEDS REBUILT
13"
S/N A-14327
MAWP 425

⑪ WORTHINGTON
VCP
NEEDS REBUILT
13"
S/N A-14328
MAWP 425

⑫ SUPERIOR
NO VCP
NEEDS REBUILT
5 3/4"
CLASS 114CD
S/N C-18551
MAWP 1500

⑬ SUPERIOR
VCP
GOOD CONDITION / MINOR REFRESH REQUIRED.
9 1/2"
CLASS 124CX
S/N 326921
MAWP 1100

⑭ GARDNER DENVER 10" MLE
VCP
NEEDS REBUILT
S/N 92475-2206
MAWP